

## Centipede / Millipede / Missile Command Speaker

A buzz in the speaker of a few Centipede / Millipede / Missile Command games has been traced to a weak ground connection on the board. The issue is not common and is easily resolved by the addition of a jumper to the board, as shown below.

**please add 30AWG jumper to back of board as shown**

